Errors						
<b>Error</b> Definition						
Comments						
Time Stamp	2006/06/05 12:48	2006/06/05 12:50	2006/06/05 12:51	2006/06/05 12:53	2006/06/05 12:55	2006/06/05 12:54
DBs	us-PGPUB; USPAT; with (ballEPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB				
Search Text	balancer and (magnet\$2 with (ball) or balls))	720/702.ccls.	720/701.ccls.	3 not 2	360/98.08,263.ccls.	5 not (2 or 3)
Hits	92	32	22	21	299	299
#	7	77	<b>L3</b>	7	L5	Le
Туре	BRS	BRS	BRS	BRS	BRS	BRS
	_		m	4	rð.	9

Errors						
Error Definition						
Comments						
Time Stamp	2006/06/05 12:55	2006/06/05	2006/06/05 12:56	2006/06/05	2006/06/05	2006/06/05 14:41
DBs	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	m .	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
Search Text	6 and (ball or balls)	6 and (balanc\$3)	310/51,67R.ccls.	US-PGPUB; USPAT; CCIS. DERWENT; IBM_TDE	(2 or 3 or 5 or 9 or 10) and (rust or corrosi\$3)	(2 or 3 or 5 or 9 or 10) and ((gas or vapor\$6) with (rust or corrosi\$3))
Hits	20	92	3355	548	101	ıçı
#7	77	87	F	L10 548	L11 101	L12
Туре	BRS	BRS	BRS	BRS	BRS	BRS

9

O

7

12

् १	<u> </u>					
Errors						
Error Definition						
Comm						
Time Stamp	2006/06/05 14:43	2006/06/05 14:45	2006/06/05 14:44	2006/06/05 15:03	2006/06/05 14:46	2006/06/05 14:46
DBs	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
Search Text	(2 or 3 or 5 or 9 or 10) and ((ball or balls) with (rust or corrosi\$3))	((ball or balls) with (rust or corrosi\$3)) and balancer	14 not 13	((ball or balls) with (rust or corrosi\$3))   with balanc\$3	17 not 5	17 not 14
Hits	m	r.	3	15	15	
#	L13	L14	L15	L17	L18 15	L19 13
Туре	BRS	BRS	BRS 1	BRS 1	BRS I	BRS I
	13	4	<b>1</b>	16	17	<b>&amp;</b>

	Type L#	#	Hits	Search Text	DBs	Time Stamp	Comm ents	Error Definition	Errors
19	BRS	L16 315		((ball or balls) with (rust or corrosi\$3)) and balanc\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/06/05 15:35			
20	BRS	L20 3		"2863780".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/06/05 15:07			
21	BRS	L21	0	((ball or balls) with (rust or corrosi\$3) with (nitrite or cyclohexylammoniu m or cyclohexylcarbamat e)) and balanc\$3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/06/05 15:37			
22	B RS -	L22 (	м	((ball or balls) with (rust or corrosi\$3) with (nitrite or cyclohexylammoniu m or cyclohexylcarbamat e))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2006/06/05			

Errors	
cents Definition	
Comm	
Time Stamp	2006/06/05 15:38
DBs	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
Search Text	((ball or balls) with (nitrite or cyclohexylammoniu m or cyclohexylcarbamate))
Hits	_
#	L23
Type L# Hits	BRS L23 54
	23